

Cause and Mechanism of Fatal Zhenxiong Landslide of January 11, 2013

by

Zhong-qi Quentin Yue

Civil Engineering Department, The University of Hong Kong, Hong Kong, P.R. China

@

International Geotechnics Symposium cum
International Meeting of CSRME 14th Biennial National Congress
November 14-17, 2016, Hong Kong




中国岩石力学与工程学会
Chinese Society for Rock Mechanics and Engineering




香港大學
THE UNIVERSITY OF HONG KONG



Acknowledgement: NSFC grant No. 41372336




The Zhaojiagou landslide suddenly occurred at 8:00 am, January 11, 2013 in Zhenxiong County, Yunnan Province, China.

A large amount of the debris rapidly arrived and instantly buried 14 village houses
46 fatalities
2 injured
59 pigs & 5 cattles buried.







Deposition of
Soil-rock
mixtures on
north gentle
slope side

3 persons

Deposition of
Soil-rock
mixtures on
south gentle
slope side

Main direction of debris flow

Relocated grass
cover from the
failed slope


18.01.2013


B



Video 1 on January 18, 2016
Landslide and debris source zone A to B area







Landslide
Source zone

Northern side

M

Main direction of debris flow

Direction and deposition of debris flow on south side

A few of the
relocated grass
cover from the
failed slope along
the main flow path

Relocated grass cover from the failed slope

18.01.2013

at C to D
**The back-steep slope of small
mount of 4 to 5 m high
by deposition of debris flows**

**Main direction
of debris flow**

18.01.2013




Video 2 on January 18, 2016
Debris flow and deposition B to D area



Many relocated grass cover
from the failed slope on both
sides of the main flow path

A few of the relocated grass
cover from the failed slope
along the main flow path



Road

E

Damage and fatality area

The grass and shrubs of the original natural slope

A few of the relocated grass cover from the failed slope along the main flow path

Main direction of debris flow

D

18.01.2013


土石移动中部C点下方的大量被运移来土石体形成的新隆起高坡地带

**Presence of
the grass and shrubs of the original
natural slope**



Main direction of debris flow

18.01.2013



Buried Village Houses

Road

**Presence of
the grass and shrubs of
the original natural
slope**


E

Main direction of debris flow

D


Few of the relocated grass
cover from the failed slope
along the main flow path

18.01.2013



Video 3 on January 18, 2016
Debris Flow & Deposition D to E area





Boundary of debris deposition

Bedrock Horizontal bedding

D

Presence of the grass and shrubs of the original natural slope

Southern

Old slide scarp

Boundary

Northern

Main direction of debris flow

Few of the relocated grass cover from the failed slope along the main flow path

Village Buried Village Zone


E

Small Pool


18.01.2013

Summary of the Field Observations on January 18, 2013

- 1) The failed natural slope site is a typical part of the mount slopes of 8 km long and has been stable for many years and was not considered unstable at all.
- 2) The debris is the old landslide debris of soil and rock mixtures (colluvium).
- 3) The debris are mainly loosely deposited on the vast gentle natural slope
- 4) These natural slopes have noticeable presence of dry soils and vegetation covers.
- 5) The debris generally has low water content and is in loose state.
- 6) There is almost no sign of slipping and water flow.
- 7) Some soil-rock mixtures are stuck together and form blocks with wet water content.
- 8) The debris has high clay contents with good cohesion.
- 9) There are many directional depositions of new and thin soil covers with roots and vegetation on both sides of the main debris flow path.




Likely mode and sequence of the fatal landslide




Likely mode and sequence of the fatal landslide

**Failed slope: $14^\circ \sim 30^\circ$ &
volume $\sim 0.25 \times 10^6 \text{ m}^3$**



Why?


Surface water flow was not a key factor due to very small catchment



Landslide site



No Free Water and Mud on the Photographs taken on Jan. 11, 2013



White
Smoke
?

Properties of Soil and Rock Mixture (Jan. 18, 2013)


Video 4 for dry debris




Video 5 for wet debris



**In dry season and no free water,
so, water was not the main cause
factor!**



For the soils,
Liquid limit 50-60%
Plastic limit 30-40%




So, what is the main cause factor ?

Witnesses of Local People

- 1) Before its failure, the failed natural slope had smoked out white gas.
- 2) There was a very high explosion sound during the failure.
- 3) The failure looked like an eruption of volcano. It suddenly erupted. A strong gas flow from the failed slope could be felt.
- 4) Large clouds and dusts were appeared above the failed slope.
- 5) The hill soil and rock mixtures were rapidly coming down and buried the village, like end-tipping of large amount of sands from a truck.
- 6) A coal-truck driver observed the whole dramatic, rapid and long-distance process of the slope failure. He did his best to run to inform the villagers but failed due to the rapid flying down of the debris.
- 7) Since the failed slope was near the coal mining area, many people believed it was related to the explosion of the methane gas in the coal mining tunnels.

Possible scenery of migration, accumulation and eruption of highly compressed gas in the gentle natural slope to cause the fatal landslide

**Failed slope: $14^\circ \sim 30^\circ$ &
volume $\sim 0.25 \times 10^6 \text{ m}^3$**



Many thanks to you for your attention!